



---

---

## SALES BULLETIN

---

---

Bulletin No. 12-04  
December 19, 2012

To: Ransburg Distributors

Subject: Vector Coded Low Pressure Hand Gun Fluid Return Spring (P/N 80141-00)

When we initially introduced the new 2k packing design for the Vector coded guns, we utilized a higher rate fluid return spring (P/N 78824-00) to allow for a more positive fluid shut-off when the applicator is not triggered.

Per requests from end users, we are replacing the old style spring with a new lower rate fluid return spring, P/N 80141-00 that only requires 3.5 lbs. trigger actuation force versus the old style spring, which required 7 lbs. of trigger force. Although our new spring (P/N 80141-00) is a lighter spring, it continues to provide a positive fluid shut-off.

All new needle shaft assemblies or applicator assemblies ordered from the Ransburg manufacturing facility after January 7, 2013, will be shipped with this new fluid return spring.

Part Number	Description	List Price
80141-00	Fluid Return Spring	\$4.25
79629-00	2k Packing Repair Kit	\$109.50
79599-01	Needle Shaft Assembly	\$511.25
79599-02	Needle Shaft Assembly	\$511.25

320 Phillips Ave  
Toledo OH 43612-1467

419-470-2000 OFFICE  
419-470-2233 FAX

finishingbrands.com  
■ devilbiss.com  
■ ransburg.com  
■ bgk.com  
■ binks.com