
SERVICE BULLETIN

Bulletin No. 03-09
March 31, 2009

To: ITW Ransburg Distributors

Subject: Fluid Nozzle O-Ring on Vector Solo Cordless Guns

The o-ring on the fluid nozzle (79377-xx or 79552-xx) is no longer required. Any future shipments of Solo applicators models 79900, 79901 and 79965 will not have the o-ring shipped installed. The design of the Solo is such that the o-ring had little or no effect on the fan pattern size.




Figure 1 SOLO R90/R70 O-RING REMOVED DIAGRAM

If you have an older Solo model, when you perform maintenance on the product, the o-ring should be removed. Insure that when the nozzle is re-installed it is properly torque in place.