

## SERVICE MANUAL ADDENDUM--A-02-06.01


NOTE: This addendum has been issued to be included with *Service Manual LN-9244-03*, *RMA-202 Robot Mounted Rotary Atomizer*.

## **Break-Away Feature**

The RMA-202 assembly is equipped with a break-away feature to minimize the damage to the atomizer, robot, etc. If a collision occurs, the six (6) plastic break-away screws fail and the atomizer will break free. This will leave the break-away ring and the mounting ring attached to the robot. A tether will be activated which is connected to the atomizer and the break-away ring, preventing the atomizer from failing. This feature can be disabled by replacing the six (6) break-away screws with six (6), glass filled nylon, 1/4-20 X 1/2" long, fillister head screws (LSFA-0004-16F).

SERVICE KIT & ACCESSORY OPTIONS	
Part #	Description
AER4019	Air Bearing Rebuild Kit
LSFA-0004-16C	Screw, 1/4-20 X 1/2" Long, Fillister Head, Glass Filled Nylon 🗈
A10568-XX	Teach Bracket Kit


Used as replacement screw option for 77524-00 break-away screws (Tighten 3-5 lbs•in)





78982-00 FLUID TIP TOOL (SUPPLIED WITH ATOMIZER)

ROBOT ADAPTER (Not Included With Kit)	
Part #	Description
A10568-01	For Use With 30mm Bell Cup Atomizer
A10568-02	For Use With 57 & 57 "V" Bell Cup Atomizers



<sup>\*\*</sup> Robot adapter not included with Kit.

## Manufacturing

1910 North Wayne Street Angola, Indiana 46703-9100 Telephone: 260/665-8800 Fax: 260/665-8516

Technical/Service Assistance

 Automotive Assembly and Tier I
 Telephone: 800/ 626-3565
 Fax:419/ 470-2040

 Industrial Systems
 Telephone: 800/ 233-3366
 Fax: 419/ 470-2071

 Ransburg Guns
 Telephone: 800/ 233-3366
 Fax: 419/ 470-2071

Technical Support Representative will direct you to the appropriate telephone number for ordering Spare Parts.



